

Modifikation Maestro 32/96 with booting problems

Please note that proper care and attention must be paid when replacing the C58 capacitor, due to the 4-layer architecture of the sound card. Attention MUST also be paid to the polarity of the electrolyte capacitor. As a guide, the area on the top of the board marked in white must match the negative pole of the capacitor. The electrolyte capacitor is a standard component with the following specification: 1 uF, 16 volt and upright design.

